

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 10/08/2014
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155658	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 B. WING _____		(X3) DATE SURVEY COMPLETED R 10/02/2014
NAME OF PROVIDER OR SUPPLIER WESLEY MANOR HEALTH CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE 1555 N MAIN ST FRANKFORT, IN 46041		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	<p>INITIAL COMMENTS</p> <p>A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 08/05/14 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).</p> <p>Survey Date: 10/02/14</p> <p>Facility Number: 001152 Provider Number: 155658 AIM Number: 200221050</p> <p>Surveyor: Phillip Komsiski, Life Safety Code Specialist</p> <p>At this PSR, Wesley Manor Health Center was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire, and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 18, New Health Care Occupancies and 410 IAC 16.2. The facility was surveyed under Chapter 18 due to the extensive renovation of the health care wing located in the original building identified as F and the addition of two new wings G and H in 2005.</p> <p>This facility was surveyed as two buildings because of different construction types. The F wing, located on the ground and first floors of a four story fully sprinklered building with a basement was determined to be Type II (222) construction. G and H wings were one story, fully sprinklered and determined to be Type II (000) construction. The facility has a fire alarm system with smoke detection in the corridors, spaces</p>	{K 000}			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 10/08/2014
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155658	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 B. WING _____		(X3) DATE SURVEY COMPLETED R 10/02/2014
NAME OF PROVIDER OR SUPPLIER WESLEY MANOR HEALTH CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE 1555 N MAIN ST FRANKFORT, IN 46041		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	<p>Continued From page 1</p> <p>open to the corridors and hard wired smoke detectors in resident rooms. The facility has a capacity of 96 and had a census of 86 at the time of this survey.</p> <p>All areas which provide customary access to residents were sprinklered. All areas which provide facility services such as the laundry, generator room, boiler room and maintenance department were not sprinklered.</p> <p>Quality Review by Dennis Austill, Life Safety Code Specialist on 10/07/14.</p>	{K 000}			